

# ChillCo, Inc.

## *Comprehensive Cooling Solutions*

### **Customer**

Casino Resort in Mississippi, U.S.A.

### **Problem**

Three 650 ton centrifugal chillers were stored in a 45' shipping container for 5 years. Gulf saltwater (remnants of hurricane Georges) caused moderate to severe metal degradation. All electrical components and control wiring were corroded beyond repair.

### **Recommendation**

Units were disassembled, all operating components either refurbished or replaced as necessary to return to design specifications, controls were upgraded, vessels were sandblasted, painted and reinsulated, then units were test-run, logged and prepared for shipment.

### **Installation Notes**

6 weeks upon receipt of the machines, they were ready to ship back to the owner. Total expenditure was less than the cost of one new machine.

### **Photos**

1. Three units jammed into a 45' shipping container.
2. Machines ready for delivery.

